

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL001140	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 08/05/2015
NAME OF PROVIDER OR SUPPLIER CREEKVIEW FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 3524 DICKEY MILL ROAD MEBANE, NC 27302		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 153}	Continued From page 1 Forward proof of completed work with you plan of correction. **08/05/2015 - RB/RF: This deficiency remains uncorrected. At the time of the survey, the drawer was being held in place with duct tape. This deficiency must be corrected. Provide to our office any supporting documentation that verifies the completed work.	{C 153}		
{C 174}	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: NEW DEFICIENCIES 1) On the rear of the home, the doors from the den leading to the porch/deck have rotted wood below the glass on the lower sections of both doors. Provide to our office any supporting documentation that verifies the completed work. 2) The carpet in the den leading to the rear of the home is extremely stained. Contact a qualified technician to have the carpet cleaned. Provide to our office a receipt from the carpet technician that verifies the completed work.	{C 174}	**RB/RF The air exchange vent for the furnace and water heater closet is in need of cleaning and painting or replacement.	